

# NOTICE TO MARINERS



## Notice of Activity on Seagreen Offshore Wind Farm

Date of Issue	<b>08/11/2023</b>	Notice Number	<b>19/2023</b>
---------------	-------------------	---------------	----------------

### Seagreen Offshore Wind Farm – Site Demarcation Buoy Top-sides destroyed.

#### Contact Details for Marine Coordination and Fisheries Liaison

The following contact can provide more information if required:

Telephone Number, 24/7	+44 (0) 1674 689401
Duty Marine Coordinator	seagreenmarinecoordination@sse.com
Address	Seagreen Wind Energy Ltd, Windy Waves House, Montrose Port Authority, South Quay Ferryden, Montrose, Angus DD10 9SL.

Fisheries liaison is coordinated by Brown and May Marine Ltd. For all fisheries enquiries, John Watt is primary contact:

Telephone Number	+44 (0) 1379872144
Mobile number	+44 (0) 7590 880746
Email	John.Watt@Brownmay.com
Address	Brown and May Marine Progress Way Mid Suffolk Business Park Eye, Suffolk IP23 7HU

### 1. Activity Description

A Seagreen Offshore Wind Farm site demarcation AIS cardinal mark buoy topsides have been destroyed due to storm damage, the buoy is unlit with AIS services unavailable. The buoy mooring remains in position. The co-ordinates are below in table 1 and shown in fig 1.

# NOTICE TO MARINERS



ID	Latitude (DDM WGS 84)	Longitude (DDM WGS 84)
Seagreen AIS East Cardinal mark	56° 31.848 N	001° 29.282 W

Table 1 – As-laid buoy coordinates.




Fig 1 – Blue arrow shows as-laid position.

## 2. Safety Zones

As all the Seagreen Wind Turbine Generators are fully commissioned, mandatory 500m safety zones shall be established around any WTG where major maintenance work is being undertaken, where major maintenance is as per the definition given in the 2007 Regulations. The safety zones will be active whenever a major maintenance vessel is at the WTG during the operational phase. Up to five of these safety zones could be concurrently active, but no more than four where there is one active 500m safety zone around the Offshore Sub-station Platform.

A mandatory 500m safety zone shall be established around the Offshore Sub-station Platform where major maintenance work is being undertaken, where major maintenance is as per the definition given in the 2007 Regulations. The safety zone will be active whenever a major maintenance vessel is at the OSP during the operational phase.

## 3. Distribution List

A central list of recipients is maintained by the Marine Coordinator; if you are not the appropriate recipient of these notices, or do not wish to receive the notices in the future, please contact us at the address included in Section 1 of this notice.