NOTICE TO MARINERS



Notice of activities associated with Seaway 7 USBL test.

Date of Issue	31-03-21	Notice Number	Seaway 7, 01-21

Seaway 7 USBL Calibration Testing

Contact Details for Marine Coordination and Fisheries Liaison

The following contact can provide more information if required:

Telephone Number (Day Operations)	+44 (0) 7932 229828
Email for Marine Coordinator	graeme.watters@sse.com
Address	Seagreen Wind Energy Ltd 1 Waterloo Street Glasgow Glasgow G2 6AY

Fisheries liaison is coordinated by Brown and May Marine Ltd. For all fisheries enquiries, Alex Winrow-Giffin is primary contact:

Telephone Number	+44 (0) 1379872144
Mobile number	+44 (0) 7760 160039
Email	Alex@brownmay.com
Address	Brown and May Marine Progress Way Mid Suffolk Business Park Eye, Suffolk IP23 7HU

1. Area of Planned Activity.

Seaway 7 will conduct a USBL calibration test at the coordinates below.

ID	Latitude (DDM WGS 84)	Longitude (DDM WGS 84)
USBL test coordinates.	56° 53.436' N	1° 37.771' W

NOTICE TO MARINERS





2. Activity Description.

Seaway 7 will conduct a USBL calibration test in the position indicated in the table in Section 1 and shown in the map above. The test is expected to commence at **06:00 on 1**st **of April 2021** and conclude at **18:00 on 1**st **of April**. The test will be conducted by the vessel Geo Ranger.

3. Vessel associated with this activity.

Vessel Name – Geo Ranger		
General Description and Dimensions:	LOA 41.7m, B 8.7m, D 2.4 m,	
Call Sign:	PHHV	
MMSI:	245893000	
Satellite communications details	N/A	
Direct Bridge/ Masters Number	+31 6 25261499	
Onshore Representative:	Peter Linden +31 6 1166 0219	

NOTICE TO MARINERS



Offshore Fisheries Liaison Officer (if applicable)

Peter Gatt



4. General Safety Advice

Geo Ranger will exhibit appropriate lights and shapes prescribed by the International Regulations for Preventing Collisions at Sea; relative to their operations. The vessel will also transmit an Automatic Identification System (AIS) message.

ALL VESSELS ARE REQUESTED to give Geo Ranger a wide berth.

MARINERS ARE REMINDED to navigate with caution and keep continued watch on VHF Ch. 70/16 when navigating the area.

5. Distribution List

A central list of recipients is maintained by the Marine Coordinator; if you are not the appropriate recipient of these notices, or do not wish to receive the notices in the future, please contact us at the address included in Section 1 of this notice.